

KING COUNTY INTERNATIONAL AIRPORT INCIDENT REPORT

INCIDENT: Fuel spill

DATE OCCURRED _____

DATE REPORTED _____

TIME OCCURRED _____

TIME REPORTED _____

LOCATION(S) OF OCCURRENCE:

REPORTED BY:

PHONE NO(S):

SUMMARY:

At approx. 0430 it started to rain. Craig Baker was notified about 0500 hours. Unable to reach Crosby and Overton. Baker stated that we should monitor the sump. If it started to fill near the level that was first observed before the pumping operation, we are to call him.

OFFICERS:

ACTION:

D.J. L...

4